



## VEHICLE CONDITION, OUTSIDE OF BVRLA FAIR WEAR & TEAR STANDARDS

Component	Condition	Repair Method	Model	Unit of Measure	Cost (Customer Charge) inc VAT
<b>SCREENS</b>					
Screen	Stone Chip	Polish	All models	Per Screen	£5.00
Screen	Scratched	Replace	All models	Per Screen	£5.00
Screen	Excessive Damage	Replace	*	Per Screen	£107.90
Screen	Excessive Damage	Replace	**	Per Screen	£159.70
Screen	Excessive Damage	Replace	***	Per Screen	£228.31
<b>BODY PANELS</b>					
Front Wheel Cover	Stone Chip	Polish	All models	Per Primed Panel	£5.00
Front Wheel Cover	Scratched	Paint & Polish	All models	Per Primed Panel	£7.50
Front Wheel Cover	Excessive Damage	Replace	*	Per Primed Panel	£78.23
Front Wheel Cover	Excessive Damage	Replace	**	Per Primed Panel	£109.97
Front Wheel Cover	Excessive Damage	Replace	***	Per Primed Panel	£288.31
Front Fairing	Stone Chip	Polish	All models	Per Primed Panel	£5.00
Front Fairing	Scratched	Paint & Polish	All models	Per Primed Panel	£7.50
Front Fairing	Excessive Damage	Replace	*	Per Primed Panel	£72.00
Front Fairing	Excessive Damage	Replace	**	Per Primed Panel	£39.86
Front Fairing	Excessive Damage	Replace	***	Per Primed Panel	£174.00
L/Front Fairing	Stone Chip	Polish	All models	Per Primed Panel	£5.00
L/Front Fairing	Scratched	Paint & Polish	All models	Per Primed Panel	£7.50
L/Front Fairing	Excessive Damage	Replace	*	Per Primed Panel	£66.56
L/Front Fairing	Excessive Damage	Replace	**	Per Primed Panel	£142.80
L/Front Fairing	Excessive Damage	Replace	***	Per Primed Panel	£205.20
R/Front Fairing	Stone Chip	Polish	All models	Per Primed Panel	£5.00
R/Front Fairing	Scratched	Paint & Polish	All models	Per Primed Panel	£7.50
R/Front Fairing	Excessive Damage	Replace	*	Per Primed Panel	£66.56
R/Front Fairing	Excessive Damage	Replace	**	Per Primed Panel	£142.80
R/Front Fairing	Excessive Damage	Replace	***	Per Primed Panel	£205.20
R/Rear Side Panel	Stone Chip	Polish	All models	Per Primed Panel	£5.00
R/Rear Side Panel	Scratched	Paint & Polish	All models	Per Primed Panel	£7.50
R/Rear Side Panel	Excessive Damage	Replace	*	Per Primed Panel	£39.96
R/Rear Side Panel	Excessive Damage	Replace	**	Per Primed Panel	£115.01
R/Rear Side Panel	Excessive Damage	Replace	***	Per Primed Panel	£111.80
L/Rear Side Panel	Stone Chip	Polish	All models	Per Primed Panel	£5.00
L/Rear Side Panel	Scratched	Paint & Polish	All models	Per Primed Panel	£7.50
L/Rear Side Panel	Excessive Damage	Replace	*	Per Primed Panel	£39.96
L/Rear Side Panel	Excessive Damage	Replace	**	Per Primed Panel	£115.01
L/Rear Side Panel	Excessive Damage	Replace	***	Per Primed Panel	£111.80

Model: \* C/G Series  
 \*\* F/R/S Series  
 \*\*\* K/R18 Series

Component	Condition	Repair Method	Model	Unit of Measure	Cost (Customer Charge) inc VAT
<b>BODY PANELS (CONT.)</b>					
Tank Trim	Stone Chip	Polish	All models	Per Primed Panel	£5.00
Tank Trim	Scratched	Paint and Polish	All models	Per Primed Panel	£7.50
Tank Trim	Excessive Damage / Corrosion	Replace	*	Per Primed Panel	£33.16
Tank Trim	Excessive Damage / Corrosion	Replace	**	Per Primed Panel	£105.01
Tank Trim	Excessive Damage / Corrosion	Replace	***	Per Primed Panel	£147.40
Tail Panel	Stone Chip	Polish	All models	Per Panel	£5.00
Tail Panel	Scratched	Paint & Polish	All models	Per Panel	£7.50
Tail Panel	Excessive Damage	Replace	*	Per Panel	£62.95
Tail Panel	Excessive Damage	Replace	**	Per Panel	£72.20
Tail Panel	Excessive Damage	Replace	***	Per Panel	£222.61
<b>CHASSIS AND MOUNTING PARTS</b>					
Rider Left Foot Peg	Stone Chip	Polish	All models	Per Item	£5.00
Rider Left Foot Peg	Scratched	Paint & Polish	All models	Per Item	£7.50
Rider Left Foot Peg	Excessive Damage	Replace	*	Per Item	£54.38
Rider Left Foot Peg	Excessive Damage	Replace	**	Per Item	£73.87
Rider Left Foot Peg	Excessive Damage	Replace	***	Per Item	£79.66
Rider Right Foot Peg	Stone Chip	Polish	All models	Per Item	£5.00
Rider Right Foot Peg	Scratched	Paint & Polish	All models	Per Item	£7.50
Rider Right Foot Peg	Excessive Damage	Replace	*	Per Item	£54.38
Rider Right Foot Peg	Excessive Damage	Replace	**	Per Item	£73.87
Rider Right Foot Peg	Excessive Damage	Replace	***	Per Item	£79.66
Pillion Foot Peg	Stone Chip	Polish	All models	Per Item	£5.00
Pillion Foot Peg	Scratched	Paint & Polish	All models	Per Item	£7.50
Pillion Foot Peg	Excessive Damage	Replace	*	Per Item	£24.96
Pillion Foot Peg	Excessive Damage	Replace	**	Per Item	£44.76
Pillion Foot Peg	Excessive Damage	Replace	***	Per Item	£65.53
Centre Stand	Stone Chip	Polish	All models	Per Item	£5.00
Centre Stand	Scratched	Paint and Polish	All models	Per Item	£7.50
Centre Stand	Excessive Damage / Corrosion	Replace	*	Per Item	£87.50
Centre Stand	Excessive Damage / Corrosion	Replace	**	Per Item	£182.70
Centre Stand	Excessive Damage / Corrosion	Replace	***	Per Item	£185.90
Side Stand	Stone Chip	Polish	All models	Per Item	£5.00
Side Stand	Scratched	Paint and Polish	All models	Per Item	£7.50
Side Stand	Excessive Damage / Corrosion	Replace	*	Per Item	£37.67
Side Stand	Excessive Damage / Corrosion	Replace	**	Per Item	£109.91
Side Stand	Excessive Damage / Corrosion	Replace	***	Per Item	£110.70
<b>ENGINE</b>					
Engine	Stone Chip	Polish	All models	Per Engine	£5.00
Engine	Scratched	Paint and Polish	All models	Per Engine	£7.50
Engine	Excessive Damage / Corrosion	Replace	*	Per Engine	£2,876.61
Engine	Excessive Damage / Corrosion	Replace	**	Per Engine	£7,204.15
Engine	Excessive Damage / Corrosion	Replace	***	Per Engine	£9,337.90
Engine Protection Bars	Stone Chip	Polish	All models	Per Item	£5.00
Engine Protection Bars	Scratched	Paint and Polish	All models	Per Item	£7.50
Engine Protection Bars	Excessive Damage / Corrosion	Replace	*	Per Item	£136.31
Engine Protection Bars	Excessive Damage / Corrosion	Replace	**	Per Item	£138.76
Engine Protection Bars	Excessive Damage / Corrosion	Replace	***	Per Item	£130.70

Model: \* C/G Series

\*\* F/R/S Series

\*\*\* K/R18 Series

Component	Condition	Repair Method	Model	Unit of Measure	Cost (Customer Charge) inc VAT
<b>ENGINE (CONT.)</b>					
Rocker Covers	Stone Chip	Polish	All models	Per Item	£5.00
Rocker Covers	Scratched	Paint and Polish	All models	Per Item	£7.50
Rocker Covers	Excessive Damage / Corrosion	Replace	**	Per Item	£134.90
Rocker Covers	Excessive Damage / Corrosion	Replace	***	Per Item	£134.40
Exhaust	Stone Chip	Polish	All models	Per Item	£5.00
Exhaust	Scratched	Paint and Polish	All models	Per Item	£7.50
Exhaust	Excessive Damage / Corrosion	Replace	*	Per Item	£395.92
Exhaust	Excessive Damage / Corrosion	Replace	**	Per Item	£505.46
Exhaust	Excessive Damage / Corrosion	Replace	***	Per Item	£601.38
<b>HANDLEBARS AND LEVERS</b>					
Handlebar Ends	Stone Chip	Polish	All models	Per Item	£5.00
Handlebar Ends	Scratched	Paint and Polish	All models	Per Item	£7.50
Handlebar Ends	Excessive Damage / Corrosion	Replace	*	Per Item	£15.85
Handlebar Ends	Excessive Damage / Corrosion	Replace	**	Per Item	£25.09
Handlebar Ends	Excessive Damage / Corrosion	Replace	***	Per Item	£33.54
Handguards	Excessive Damage	Replace	*	Per Item	£63.10
Handguards	Excessive Damage	Replace	**	Per Item	£151.77
Brake Lever	Stone Chip	Polish	All models	Per Item	£5.00
Brake Lever	Scratched	Paint and Polish	All models	Per Item	£7.50
Brake Lever	Excessive Damage	Replace	*	Per Item	£50.16
Brake Lever	Excessive Damage	Replace	**	Per Item	£58.90
Brake Lever	Excessive Damage	Replace	***	Per Item	£58.90
Clutch Lever	Stone Chip	Polish	All models	Per Item	£5.00
Clutch Lever	Scratched	Paint and Polish	All models	Per Item	£7.50
Clutch Lever	Excessive Damage	Replace	*	Per Item	£25.51
Clutch Lever	Excessive Damage	Replace	**	Per Item	£58.90
Clutch Lever	Excessive Damage	Replace	***	Per Item	£58.90
Mirrors	Stone Chip	Polish	All models	Per Mirror	£5.00
Mirrors	Scratched	Paint and Polish	All models	Per Mirror	£5.00
Mirrors	Excessive Damage	Replace	*	Per Mirror	£28.15
Mirrors	Excessive Damage	Replace	**	Per Mirror	£58.25
Mirrors	Excessive Damage	Replace	***	Per Mirror	£58.25
<b>LUGGAGE</b>					
Left Pannier	Stone Chip	Polish	All models	Per Primed Item	£5.00
Left Pannier	Scratched	Paint and Polish	All models	Per Primed Item	£7.50
Left Pannier	Excessive Damage	Replace	**	Per Primed Item	£304.20
Left Pannier	Excessive Damage	Replace	***	Per Primed Item	£525.72
Right Pannier	Stone Chip	Polish	All models	Per Primed Item	£5.00
Right Pannier	Scratched	Paint and Polish	All models	Per Primed Item	£7.50
Right Pannier	Excessive Damage	Replace	**	Per Primed Item	£304.20
Right Pannier	Excessive Damage	Replace	***	Per Primed Item	£525.72
<b>LIGHTS</b>					
Indicators	Excessive Damage	Replace	*	Per Item	£73.71
Indicators	Excessive Damage	Replace	**	Per Item	£41.22
Indicators	Excessive Damage	Replace	***	Per Item	£92.61
LED Additional headlight	Excessive Damage	Replace	**	Per Item	£86.31
LED Additional headlight	Excessive Damage	Replace	***	Per Item	£86.31

Model: \* C/G Series

\*\* F/R/S Series

\*\*\* K/R18 Series

<b>Component</b>	<b>Condition</b>	<b>Repair Method</b>	<b>Model</b>	<b>Unit of Measure</b>	<b>Cost (Customer Charge) inc VAT</b>
<b>SEAT</b>					
Rider Seat	Tear / Excessive Damage	Replace	*	Per Item	£268.90
Rider Seat	Tear / Excessive Damage	Replace	**	Per Item	£201.70
Rider Seat	Tear / Excessive Damage	Replace	***	Per Item	£261.20
Pillion Seat	Tear / Excessive Damage	Replace	*	Per Item	£158.30
Pillion Seat	Tear / Excessive Damage	Replace	**	Per Item	£182.11
Pillion Seat	Tear / Excessive Damage	Replace	***	Per Item	£247.21

Per Primed Part Additional cost for painting may be required. Please speak to your Retailer.

Model: \* C/G Series

\*\* F/R/S Series

\*\*\* K/R18 Series